

CV No.	Details of Correction.
2881	Delete all entries on this line.
2893	Delete all entries on this line.
2894	Delete all entries on this line.
2898	Delete all entries on this line.
2913	Delete all entries on this line.
2942	Delete all entries on this line.
2944	Delete all entries on this line.
3504	Delete all entries on this line.
3547	Delete all entries on this line.
3568	Delete all entries on this line.
3720	Delete all entries on this line.
3760	Delete all entries on this line.
3786	Delete all entries on this line.
3791	Delete all entries on this line.
3804	Correct "W21" to read "W21 - 7-pin".
3828	Delete all entries on this line.

2. CROSS-REFERENCE : VALVE TYPE DESIGNATION TO CV NO.

Make corrections as follows :-

Old Name	Details of Correction.
CE2	Add to list: CV No. = 1764.
CMG8	Correct CV No. to read 1432.
CX25	Add to list: CV No. = 1766.
C1B	Add to list: CV No. = 1765.
DE5	Add to list: CV No. = 2891.
GE/VL	Add to list: CV No. = 1767.
GU20	Add to list: CV No. = 1435.
HY61	Delete this line.
MU12	Delete this line.
MHL4	Delete this line.
QK26	Add to list: CV No. = 1768
SP2	Add foot-note :- "Specially selected valve for D. A/S. M. CV1320 is the normal valve".
Thermal Delay Switch A. P. 3567. }	Add foot-note :- "Specially selected DLS10. CV190 is normal switch".
UU5	Delete this line.
VMP4G	Delete this line.
VP21	Delete this line.
VT62	Add description "Pair of Valves".
VT62 Paired.	Delete this line.
POVT121A	Correct CV No. to read "1288".
X66	Delete this line.
1L4	Add to list: CV No. = 1758.
2C26A	Add to list: CV No. = 1759.
2J26	Add to list: CV No. = 1760.
3C31/C1B	Add to list: CV No. = 1765.
3FP7	Add to list: CV No. = 1761.
5BP1	Delete this line.
6AC7	Correct CV No. to read CV660.